AHEAD OF WHAT'S POSSIBLE™

CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M001139

DATE: 10-Apr-2026

# PRODUCT DISCONTINUANCE NOTICE

| Notice Type | Maxim Part Number | Recommeded Replacement | Last Order Date | Last Delivery Date | Reason |
|---|---|---|---|---|---|
| Discontinuance | PD1-140-42-SE-232 | PD42-1-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | PD2-110-42-232 | PD42-2-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | PD2-110-42-485 | PD42-2-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | PD2-140-42-SE-232 | PD42-2-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | PD3-110-42-485 | PD42-3-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | PD3-110-42-CAN | PD42-3-1240-CANOPEN | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | PD3-140-42-SE-485 | PD42-3-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-10-0214 | TMCM-1240-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-10-0217 | TMCM-1240-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-10-0218 | N/A | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-10-0219 | TMCM-1240-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-10-0393 | TMCM-1240-CANOPEN | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-11-0034 | TMCM-1636-24V-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-30-0183 | PD42-2-1240-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-30-0184 | PD42-3-1240-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-30-0214 | N/A | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-30-0219 | PD42-2-1240-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-30-0220 | N/A | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-30-0224 | PD42-3-1240-CANOPEN | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-30-0227 | PD42-2-1240-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-30-0228 | PD42-3-1240-TMCL | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMC-71-0002 | N/A | 10-Apr-2026 | 07-Oct-2026 | No Demand |
| Discontinuance | TMC-71-0008 | N/A | 10-Apr-2026 | 07-Oct-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-110-42-232 | TMCM-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-110-42-485 | TMCM-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |

**LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 11-May-2026**

| | | | | | |
|---|---|---|---|---|---|
| Discontinuance | TMCM-110-42-CAN | TMCM-1240-CANOPEN | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-110-CABLE | N/A | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-140-42-SE-232 | TMCM-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-140-42-SE-485 | TMCM-1240-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-140-CABLE | N/A | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-160-232 | TMCM-1636-24V-TMCL | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-1630-2C | N/A | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | TMCM-1630-4U | N/A | 10-Apr-2026 | 10-Apr-2026 | Part can no longer be manufactured |
| Discontinuance | VT1676SBFQ | N/A | 10-Apr-2026 | 07-Oct-2026 | No Demand |