



KYOCERA AVX Components Corporation

1 AVX Boulevard
Fountain Inn, SC 29644 USA
Phone: +1 (864) 967-2150
Website: <https://www.kyocera-avx.com>

Attention: Digi-Key

PCN-559-2022

Change Notice

Dear Valued Customer,

In order to increase capacity Kyocera AVX wish to provide notification of the plan to introduce the Kyocera AVX facility in Nakhon Ratchasima, Thailand as an additional manufacturing location for MLCC. Plant target to be IATF16949 compliant by 1st April 2023.

1. Product Type, Changes, and Customer/AVX/Alternate Part Numbers:

Change	Current Manufacturing Sites	After Change
Additional Manufacturing facility for MLCC	Penang, Malaysia, San Salvador, El Salvador Coleraine, UK Kokubu, Japan	Penang, Malaysia, San Salvador, El Salvador Coleraine, UK Kokubu, Japan Nakhon Ratchasima, Thailand

Components covered by this PCN

MLCC Automotive Range: PN with 11th digit = "4" e.g. 06035C104K4T2A Or New PN 2nd digit = "A" e.g. KAM15AR71H104KT		
Case	Voltage	Cap Range
0603	16-50V	273-104
0805	16-25V 50V 100V	474-225 104-105 104-105
FS05	16-100V	682-104
1206	25-50V 100V	684-475 124-225



KYOCERA AVX Components Corporation

1 AVX Boulevard
Fountain Inn, SC 29644 USA
Phone: +1 (864) 967-2150
Website: <https://www.kyocera-avx.com>

2. Reasons/Background:

Kyocera AVX is expanding MLCC operations.

3. Products Before and After the Change:

Samples available now.

4. Change Schedule:

Change Event	Target Completion Date	Comments
Production Start	July 1, 2023	

5. Feedback Due:

July 1, 2023

Please indicate your feedback to Kyocera AVX in writing by this feedback date.

6. Contact:

Should you have any questions or concerns, please contact

US, Zack Kozawa, [zack.kozawa @kyocera-avx.com](mailto:zack.kozawa@kyocera-avx.com)

Thank you.

May 1, 2023



KYOCERA AVX Components Corporation

1 AVX Boulevard

Fountain Inn, SC 29644 USA

Phone: +1 (864) 967-2150

Website: <https://www.kyocera-avx.com>

Customer feedback regarding the change notification:

Requests, Questions, Comments:

--

Signature of Approval	
Date	
Title	
Name	
Company Name	

KAVX P/N

06035C104K4T2A

06035C104K4Z2A

06035C683K4T2A

06035C683K4Z2A

06035C563K4T2A

06035C563K4Z2A

06035C473K4T2A

06035C473K4Z2A

06035C333K4T2A

06035C333K4Z2A

06035C273K4T2A

06035C273K4Z2A

06035C223K4T2A

06035C223K4Z2A

06031C104K4T2A

06031C104K4T2A

06031C104K4T2A

06031C104K4Z2A

06031C104K4Z2A

06031C104KAT2A

06031C104KAT2A

08055C104K4T2A

08055C104K4Z2A

08055C224K4T2A

08055C224K4Z2A

08051C104K4T2A

08051C104K4Z2A

08051C105K4T2A

08051C105K4T2A

08051C105K4T2A

08051C105K4T2A

08051C105K4T2A

08051C105K4T2A

08051C105K4T2A

08051C105K4T2A

08051C105K4T2A

08051C105K4T2A

08051C105K4Z2A

08051C105K4Z2A

08051C105K4Z2A

08051C105K4Z2A

08051C105K4Z2A

08051C105K4Z2A

08051C105K4Z2A

08051C105K4Z2A

08051C105K4Z2A
08051C105K4Z2A
08051C105K4Z2A
08051C105K4Z2A
08051C105K4Z2A
08051C105K4Z2A
08051C105K4Z2A
08051C105K4Z2A
08051C105K4Z2A
08051C105K4Z2A
08051C105KAT2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4T2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224K4Z2A
08051C224KAT2A
08051C224KAT2A
08051C224KAT2A
08051C224KAT2A

[illegible]

[illegible]

08053C225K4T2A

[illegible]

[illegible]

08055C105K4Z2A
08055C105K4Z2A
08055C105K4Z2A
08055C105K4Z2A
08055C105K4Z2A
08055C105K4Z2A
08055C105K4Z2A
08055C105K4Z4A
08055C105KAZ2A
08055C105KAZ2A
08055C105KHZ2A
08055C334K4T2A
08055C334K4T2A
08055C334K4T2A
08055C334K4T2A
08055C334K4T2A
08055C334K4T2A
08055C334K4T2A
08055C334K4T2A
08055C334K4T2A
08055C334K4T2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334K4Z2A
08055C334KAT2A
08055C334KAT2A
08055C334KAT2A
08055C334KAT2A
08055C334KAT2A
08055C334KAT2A
08055C334KAT2A
08055C334KAT2A
08055C334KAT2A
08055C474J4Z2A
08055C474K4T2A
08055C474K4T2A
08055C474K4T2A
08055C474K4T2A

[illegible]

[illegible]

[illegible]

12061C225K4T2A

[illegible]

12063C185K4Z2A

[illegible]

[illegible]

[illegible]

[illegible]

12065C475K4Z2A
12065C475K4Z2A
12065C475K4Z2A
12065C475K4Z2A
12065C475K4Z2A
12065C475K4Z2A
12065C475KAT2A
12065C475KAT2A
12065C475KAT2A
12065C475M4Z2A
12065C475M4Z2A
12065C475M4Z2A
12065C684K4T2A
12065C684K4T2A
12065C684K4T2A
12065C684K4T2A
12065C684K4T2A
12065C684K4T2A
12065F224K4T2A
12065L105K4T2A
12065L684K4T2A
12065Z475K4Z2A
12065Z475K4Z2A
1206VC224K4T2A
1206YC225K4T2A
1206YC225K4T2A
1206YC225K4T2A
1206YC225K4Z2A
1206YC225K4Z2A
1206YC225K4Z2A
1206YC225K4Z2A
1206YC225K4Z2A
1206YC225K4Z2A
1206YC335K4Z2A
1206YC475K4T2A
1206YC475K4T2A
1206YC475K4T2A
1206YC475K4Z2A
1206YC475K4Z2A
1206YC475K4Z2A
AP065C684JQT2A
AP101C105KQX2A
AP103C106KQT2A
AP105C225KQT2A
ESD53C105K4T2A-26
ESD53C105K4T2A-26
ESD53C105K4T2A-26
ESD53C105K4T2A-26

FS051C104K4Z2A

FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z2A
FS051C104K4Z4A
FS051C104K4Z4A
FS051C104K4Z4A
FS051C104K4Z4A
FS051C104K4Z4A
FS051C104K4Z4A
FS051C104K4Z4A
FS051C104K4Z4A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C223K4Z2A
FS051C273K4Z2A
FS051C273K4Z2A
FS051C473K4Z2A
FS051C473K4Z2A
FS051C473K4Z2A
FS051C473K4Z2A
FS051C473K4Z2A

FS051C473K4Z2A
FS051C473K4Z2A
FS051C473K4Z4A
FS051C473K4Z4A
FS051C473K4Z4A
FS051C473K4Z4A
FS051C683K4Z2A
FS051C683K4Z4A
FS051C683K4Z4A
FS055C103K4Z2A
FS055C103K4Z2A
FS055C103K4Z2A
FS055C103K4Z2A
FS055C104K4Z2A
FS055C104K4Z2A
FS055C104K4Z2A
FS055C104K4Z2A
FS055C104K4Z2A
FS055C104K4Z2A
FS055C104K4Z2A
FS055C104KAZ2A
FS055C104M4Z2A
LD061C105KAB2A
LD065C105KAB2A