



TE Connectivity

Product Change Notification: PCN-24-198741

PCN Date: 14-MAR-24

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

Product Description: (Text limited to 120 characters)
HVP-HD1400 series(PowerTube) Plug TPA


General Description of Changes

Design modification to optimize process assembly


Small rib in plug TPA




Remove rib in plug TPA




Small rib in plug TPA




Remove rib in plug TPA



Small rib in plug TPA



Remove rib in plug TPA



Other attachments:

[PLUG TPA CHANGE INFO](#)

Reason for Changes:

Update made to products function

PCN Attributes:

Product Category:

Hems Products

Kind of Change:

Geometry

Change Feature:

Special Design Feature

Potential Customer Impact:

No Customer Impact

Remarks:

Estimated Dates:

Last Order Date (Obsolete Parts Only):

First Ship Date of Changed Items (Changed Parts Only):

01-MAY-2024

Last Ship Date of Changed Items (Obsolete Parts Only):

Last Date for Mixed Shipments: (Changed Parts Only):

01-OCT-2024

Effectivity Date:

Date of First Samples:

01-MAY-2024

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
2399663-1	NO						
2399663-2	NO						
2399663-3	NO						
2399663-4	NO						
2399663-5	NO						
2399663-6	NO						
2399663-7	NO						
2399663-8	NO						