PRODUCT CHANGE NOTIFICATION

Product Category OUTLETS **20230620-1**

Product Group ROAR

ISSUE DATE: 20-Jun-23

IMPACTED REGIONS: ☑ NA ☑ EMEA ☑ LATAM ☑ AP

REASON FOR CHANGE: ☑ DISCONTINUATION ☐ OTHER

DESCRIPTION OF CHANGE: (Required)

Some Outlet products are being discontinued.

Photos/Drawing (where applicable)

IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)

Reference Page 2 / Linked PDF

DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date			
Old product discontinuation date*			

***Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Compatibility Type	Replacement Part 1	Replacement Part 2
NK2HSFAWY	Compatible	NK2HSFIWY	
CHF1MEI-X	No Replacement	NO-REPLACEMENT	
NKUKS4AW-2G	Compatible	NKUKS4SAW-2G	
KP24APWSBL	Compatible	KP24WSBL	KPA24WSBL